




**Buildbotics**



The Buildbotics CNC Controller is built for compatibility, ease of use, and performance. The hardware and software are completely Open-Source.

## Electrical Connections

The Buildbotics CNC Controller has a DB25 I/O port on the back for making a variety of I/O connections. A DB25 breakout box is used for making connections to the DB25 connector, and is included with the controller.



**Plug the DB25 Connector into the back of the Buildbotics Controller like this.**




To connect the Endurance Laser to the Buildbotics Controller, simply connect the PWM+ wire from the

Laser Controller to the "Tool PWM" line found on pin 17 of the Breakout Box and connect the PWM-wire from the Laser Controller to one of the Ground pins on the Breakout box (pin 7 is a good choice). Then plug the DB25 Breakout board into the back of the Buildbotics Controller.

## Configuration

Next, simply select “Tool” from the sidebar on the web (or local) interface to open the “Tool Configuration” page.



With “Tool Configuration” page open, make the following configuration changes:

1. Select “PWM Spindle” in the “tool-type” field.
2. Leave “tool-reversed” unchecked.
3. Set “max-spin” to 255.
4. Set “min-spin” to 0.
5. Leave “tool-enable-mode” and “tool-direction-mode” disabled.
6. Leave “pwm-inverted” unchecked.
7. Set “pwm-min-duty” to 0.
8. Set “pwm-max-duty” to 100.
9. Set “pwm-freq” to 1000.

The click the green “Save” button to save the changes.