

**ChinaCNCzone**

**Mini CNC Router Machine Manufacturer**  
**Look for worldwide distributors**

Web: <http://www.chinacnczone.com/> Phone: 86-755-83692414 Mail: [sales@chinacnczone.com](mailto:sales@chinacnczone.com)

Address: Nankeng First Industry Park, Bantian, Longgang District, Shenzhen, China

## User guide for CNC 3040 Series



# CONTENT

Main features for this mini CNC router machine CNC 3040Z-DQ V2.....	- 2 -
How to use CNC 3040Z-DQV2 .....	- 4 -
1. Software.....	- 4 -
2. How to set the software: .....	- 10 -
3. Try to use your CNC .....	- 17 -
4. To know the engraving bits in common use.....	- 27 -


**Main features for this [mini CNC router](#) machine CNC 3040Z-DQ V2**

Ball Screw

4 Axis

230W DC spindle

Limited switch added



Auto checking function added



**Notice:**

1. This machine should be used with the PC parallel port and controlled by Mach 3 or other software. The PC parallel port should work in condition of the EPP mode, the setup of the EPP mode should be applied on the main board BIOS.

2. You'd better use the PC to control the machine, especially for this machine and do not install other software if conditions permit. **And please do not use the Laptop to control the machine**, the battery of some laptops will impact the pulse signal of the machine and the voltage of some parallel port is very low, it will cause the lost of the signal.

**Warn:**

You should setup the software correctly; it will make the machine works well. If you do not do it well and try to run the machine, it may damage the machine or cause the danger.

When you install or setup the machine, please do not turn on the control box, it may cause some damages.

Please do not put the connectors on the control box, when it is power on. You should regulate the spindle as the low speed when you want to restart it. The interval of the open/close button time should be at least 30s, when you restart the spindle or turn on the control box again, otherwise it will cause the damages of the control box.

Our machine is **220V or 110V**, when it is power on, please do not open the control box, do not touch the wiring connectors and not touch the running cutters, please wear the glasses or mask to protect yourself.

Main technical details for CNC 3040Z-DQ V2 are as below:

<b><u>CNC 3040Z-DQ V2</u> technical details</b>	
X,Y,Z Working Area:	275×385×55mm
Max. Feeding height:	≤70mm
Outside dimension	610×480×400mm
Table size	530×320mm
Lathe structure	6061/6063 Aluminium alloy
Stepping motor	two-phase 57/1.8A
Drive unit:	1204 Ball Screw
Sliding unit.:	Chromeplate shaft
Maximum speed:	0-4000mm/min
Engraving speed:	300-2500mm/min
Repeat positioning Accuracy:	0.05mm
Spindle motor:	spindle motor with direct current(200w)
Spindle speed:	1000~8000RPM/MIN
Cutting tool-holder:	ER11/3.175mm
Interface:	Parallel port
Software Compatability:	Mach3/Emc2,(Type3,Wentai, ArtCAM)
Command code:	G code/.nc/.ncc/.tab/.txt

Machine weight:	28kg (including packaging)
Outside packing	62x58x48CM


# How to use CNC 3040Z-DQ

## 1. Software


1. Open the Mach 3 file; double click the “Mach3xxxxx.Exe”to start.




2. Click the “Next”




3. Click the "Yes"




4. Click the "Next"




5. Click the "Next"




6. Click the "Next"




7. Click the "Ok"




8. Click the "Finish"



9. Click the "Ok"



10. Click the“Ok”




After installing the Mach 3, on the desktop, there will occur 3 icon as follows:



**Notice: do not open them, please restart your PC at first (if you open the software not restart PC, it need uninstall fully and reinstall it)**


After restarting the PC, please double click the “**MACH 3 MILL**” icon, then you can enter the setup of the software (you can delete the other two icons Mach3 and Mach3Turn)

Open the G code---all the axis should be“0”---then start to engrave, You can choose the “Feed hold” to pause the working when it has something, if something emergency happens, you can use the “Reset” or you can adjust the “Feed rate”.




## 2. How to set the software:


1. After restarting the PC, choose the **MACH 3 MILL** icon on the desktop to start the Mach 3.
2. Open the “Config-- selects Native Units” menu, and then choose the “MM’s”



3. See as below, open "Config--Ports and Pins" to enter the setup.




4. To check whether all the data is same as the follows in the big red circle and then choose OK to continue.







6. The clients who bought the Control box from us, need to setup the E-stop signal, still in “Ports and Pins” menu to click “Input Signals” to find the “Estop”, then setup as follow, final apply and then save. ( **Emergency setting** )




7. Limited Switch setting in “Ports and Pins” menu to click “Input Signals” and set X, Y, Z as below:




8. Output signals setting in “Ports and Pins” menu to click “Output Signals”, set as below, and then save.




9. Spindle setup in “Ports and Pins” menu to click “Spindle Setup”, set as below, and then save.



10. The setup of the Stepper motor: Config-- Motor Tuning--- X Axis---setup the X axis as follows---then“SAVEAXIS SETTINS”, then s etup the Y axis and Z axis,final click “OK”.**X Axis, Y Axis, Z Axis parameters should the same.**






The setup is over, Please close the Mach software that all data setup can be available. And then open it again to check whether all the data is correct otherwise can't run your machine well.

### 3. Try to use your CNC

1. First let us to learn this machine, below take 3020 for example, The full kit has the machine(the Frame), the electrical control box, X,Y,Z stepper motors, the spindle and the spare parts box(it contains the 4 pcs presser feet, 5 pcs test bits, 1 pair of spare carbon brush, 1 pcs fuse pipe,ancethe spanner of the spindle, the 6 hexagonal spanner and the nuts and screws).





- (1) Our machine is made of the aluminum alloy, if you drop it from the top on the floor or hard hit, it will damage the machine. Please put this machine on the stable desk, the thin desk may cause more resonance when it is running.
- (2) In the electrical control box, there are the switching power supply, stepper driver board, the spindle speed regulator, please put it in a ventilating condition and around it, there should not have the electromagnetic interference within 10 meters.
- (3) Please sort out the power cables and connecting cables, do not put it in a mess, maybe it will obstruct the working of the machine. Please remain some excess of the cable for the gantry and the X axis.
- (4) Please try to study yourself and test it, If you have some questions, you can ask us or discuss it on the CNC Forum

## 2. The wiring and yourself-checking

### (1) Wiring:

Put the cables into the corresponding port, on the connectors there print the X, Y, Z, the cable of the spindle has no mark, but it is a two-wire plug. On the electrical control box, it prints the marks of the ports. The LIMIT-IN is the spare port for the 4th axis or external limit switch or E-stop etc.

Now just connect the X, Y, Z stepper motor cables and the spindle cable, but the parallel cables do not connect it at first.

Please make sure that all the connectors are tight to avoid the loose contact.



## 2. Yourself-checking

The aim of the checking is to make sure that the electrical control box and the machine are well wired and all axes can be controlled.

At first, power off the spindle and the driver power, “o” is off, “I” is on, and regulates the spindle in this safe position (see the photo below). The E-stop switch is off.

Then wrest the X axis screw by hand to feel it (at this time you can move it easily), and then connect the power of electrical control box and open the driver switch, at the time, you can hear a small voice of the moving of the X, Y, Z stepper motors. Now try to move the X axis screw to check whether you can move it easily by hand, if it does not move, it means this axis have been controlled by the control box, after this, please try to move the Y, Z axis screw(move the coupling is ok), if they cannot be moved, it means all axis are self-locked and fine.



If anyone screw can be moved, please check the wiring of this axis to see whether it is well connected, if the 3 axis all can be moved, please contact us. if 3 axis are ok please continue.

Then please power off the driver and make sure the spindle is in the safe position. Power on the spindle and adjust clockwise slowly of the spindle speed regulator to the first dot, the spindle motor will start to move, continue to adjust clockwise, spindle will run more and more quickly.

Remark: If you face the spindle, the clockwise direction is the right direction. If you find the direction is anticlockwise, please power off the spindle and exchange the two connectors will be fine.



**Notice:**

(1).When the spindle is power-on, the voltage between the two connectors of the spindle is 90VDC, when the spindle is running, please do not touch the cutters and wear the glasses and mask. Please keep the children away from the machine.

(2) Before powering on the spindle, please make sure the spindle speed regulator is in the safe position and then power on the spindle and speed up slowly. When power off the spindle, you can turn off the spindle power supply switch directly and regulate the speed regulator to the safe position. If the speed regulator is in the high-speed position, it will cause the brunt of the fuse and over current, this will do damage to the speed regulating board in the control box.

**3.Test by PC**

(1)In the power off, use the parallel cable to connect the control box and the PC parallel port.

(2) Start the PC, open the “MACH 3 mill “and the drive power, and make sure the 3 axis are self-locked automatically. Check the Mach 3 interface, the E-stop button is twinkling, if so, click it to stop it (if you click it, and the E-stop button on the interface is still twining, please check the E-stop button on the control box is pressed, if it is pressed, please move it clockwise to make it unpressed,if the driver is power off the E-stop button is twinkling and can't stop).

(3) After stopping twinkling E-stop on MACH 3 interface, you can type the direction key of the PC keyboard, to check whether the X, Y, Z axis can move.


If it cannot move: A-check the X, Y, Z data on the Mach 3 is changed or not when typing the direction key on the keyboard, if the data changes but the X, Y, Z axis do not move, please follow the step as below:

B-check the setup of the pin.


C-check the connection of parallel cable

D-check the manual control button “JOG ON/OFF”whether is green. Refer the image below

E-contact us



If all the axis can move, please check the direction of the axis coordinate is right (see below).  
 If you find the axis which move wrong direction please changes the setup as Page10 green letters?



PS: you can use the keyboard to control the direction of the axis, and also you can use the manual control keyboard of Mach 3 by using the mouse to control the movement of the X, Y, Z axis.  
 Press the "TAB" key on the keyboard then it will pop-up the MACH manual control interface as the figure below.



Press Tab key to enter the manual control and press again to exit it



continue motion and Jog mode

Jog mode unit distance/mm

The direction control of X,Y,Z axis

Now the test of the Mach 3 communication with the machine is over. If it still can not realized the manual control, please do as follows:

- (1)Uninstall the Mach3 and use other versions of the Mach 3 to test(because some parallel port is not compatible with MACH software)
- (2)Check the PC parallel port is fine or change another PC to test it.
- (3)If the machine' X, Y, Z axis can be self-locked, you should think about the compatibility of the PC and the Software.
- (4) You must restart the PC when finish installing of the MACH 3.

#### 4. Engraving test

We use a Chinese character "雕" to test the machine.



First: Assembly the materials

- (1) Find a soft material about 12CM\*12CM, like PVC, WOOD, PMMA or other plastic material
- (2) Fix the board on the working table as below, notice the screw and nuts should be tight but do not make the T slotted board out of shape.




Second: Cutter trace unload running test without the cutter

- (1) Copy the document you want to engrave to the desktop of your PC, and then open the Mach 3 Mill---start the G code and import the document you want to engrave, also you can use the Mach menu---file---load G code to import it.



(2) Import the G code of "雕", then it will display on the PC as below




(3) Power on the control box driver, move the spindle tool bit to the left-bottom of the material board by manual control the three axis, the area in the red circle (the image below) is the safe area. The left bottom red-green WCS arrowhead above is the original point, move the spindle bit (without cutter) to this point.

(4) Put the Z axis a little higher to avoid touching the clamping nuts. Clear all the axis to zero and click the Green (ALT-R) button to start. At the same time, please pay attention to the windows of the software, the moving dashed is the trace of the machine. If you find the trace is incorrect, please power off the drive and check the unit of the Mach 3 whether is "MM" and axis WCS.

(5) This test engraving dimension is 7\*7CM, 1MM thickness, engrave it twice, each time the depth is

0.5MM, so it will work twice the same trace, when it idle running, please check whether it will touch the clamping board, if so, please recheck the original point of the engraving, Otherwise it will damage the cutter, the material even the machine.




**Notice: when doing holed-out work, please put a no-use flat board below the material to avoid the damage of the working station**

### **3. Engraving test with the cutter bits**

(1) Install the cutter bits: after the idle running test without the cutter bit is fine, we can put the cutter bit on the spindle; the cutter bit is SHK---3.175mm---30 degree---0.3mm---flat bottom engraving bits. The shank should be put into the collet more than 1 CM and fix it tightly by wrench.

(2) Tool setting: It is very important to fix the cutter bits point to the original point of the material. Where is the original point it is according to your G code file setting, our example is in the position of the left-bottom of the material board. You can power on the drive on the control box and move the cutter bits to that point by hand axis as below.



The engraving steps:

(1) Power on the drive and move the X, Y, axis to the original point by hand put the Z axis down to the material board, distance is about 1 CM with material board

(2) Power off the drive on the control box, and put a small piece of paper on the original point and move the Z axis by hand, and put the Z axis down, when the bit point is closed to the paper, you can feel the paper is touched by the bit point but the bit point is not touch the material, this tool setting tolerance is about 0.05MM (if you need more precise, you can buy a professional tool presenter)

(3) After it, power the drive on the control box and all axes will be self-locked.

(4) Make sure the spindle speed regulator is in the safe position and power on the spindle and move the speed regulator slowly, for the first time you can move it to highest speed (the biggest point around the speed regulator) to check whether the full speed running of the spindle is fine.

(5) Make sure you wear the face mask (at least cover for the eye protection), then click the "Alt-R" to engrave in MACH3.

Remark: During the machine is working, if something emergency happens please press the E-stop button on the control box or Click the E-stop button in the Mach 3.

#### **4. To know the engraving bits in common use**

(1) ACRYLIC cutting process, we suggest use one spiral flute bits, its advantage is no smoke no smell, high speed, high efficiency, on-stick powder, thin lay of cutting, smooth surface material board, if the material is thin ACRYLIC like as 2-3mm thickness, two spiral flute bits or straight bits are suitable too

(2) Aluminum board cutting process, we suggest use one spiral flute bits for

aluminium,non-stick, high speed, and high efficiency. If low cutting required or hard aluminum (non-stick bits aluminum), also can choose two spiral flute bits for metal

(3)Small precision 3D engraving in the non-metal material, we suggest use radiuses bottom engraving bits

(4)Large 3D engraving in soft wood,MDF board,native wood,PVC,Acrylic we suggest use one or two spiral flute ball bits

(5)Engraving metal,it need use one or two spiral flute bits for metal,flat bottom engraving bits for steel

(6)Engraving for MDF board,solid wood, composite board, plywood we suggest use straight flute bits or two large flute spiral bits

(7)Engraving for metal mould it need use flute end mills

(8)Engraving for stone it need use diamond router bits

If you have some more questions for router bits please consult professional router bits supplier.

### **Contact Information**

**Web:** <http://www.chinacnczone.com/> **Phone:** 86-755-83692414

**Mail:** [sales@chinacnczone.com](mailto:sales@chinacnczone.com)

**Address:** Nankeng First Industry Park,Bantian,Longgang District,Shenzhen, China