


## Endurance laser box ver 2.0



**WARNING! PWM duty cycle should not exceed 99%. Unused wire of PWM to reduce interference need to twist at the end (black with red)**